

Volunteer Water Information Network Summary - Haywood County, 1996 - 2008

Site	Stream	Year 1 1996-97	Year 2 1997-98	Year 3 1998-99	Year 4 1999-00	Year 5 2000-01	Year 6 2001-02	Year 7 2002-03	Year 8 2003-04	Year 9 2004-05	Year 10 2005-06	Year 11 2006-07	Year 12 2007-08	Year 13 2008-09
Richland Creek and Jonathan Creek Watersheds														
13	Allens Creek	91 Excellent	75 Average	83 Good	81 Good	92 Excellent	87 Good	87 Good	87 Good	96 Excellent	98 Excellent	98 Excellent	98 Excellent	98 Excellent
8	Eaglenest Creek	84 Good	82 Good	77 Average	78 Average	67 Below Average	68 Below Average	68 Below Average	74 Average	74 Average	67 Below Average	74 Average	78 Average	74 Average
21	Hyatt Creek upstream			47 Poor	49 Poor	51 Poor	51 Poor	53 Poor	51 Poor	51 Poor	51 Poor	51 Poor	53 Poor	51 Poor
22	Hyatt Creek downstream			57 Poor	55 Poor	50 Poor	53 Poor	50 Poor	52 Poor	50 Poor	56 Poor	56 Poor	56 Poor	56 Poor
28	Hyatt Creek Left Branch									52 Poor	72 Average	65 Below Average	65 Below Average	65 Below Average
29	Hyatt Creek Owl Ridge Branch									56 Poor	60 Below Average	56 Poor	56 Poor	56 Poor
30	Hyatt Creek Green Valley Branch									47 Poor	58 Poor	52 Poor	52 Poor	52 Poor
9	Plott Creek	84 Good	84 Good	82 Good	81 Good	78 Average	69 Below Average	69 Below Average	69 Below Average	81 Good	81 Good	81 Good	83 Good	83 Good
23	Ratcliff Cove Branch					78 Average	76 Average	74 Average	74 Average	67 Below Average	63 Below Average	67 Below Average	67 Below Average	67 Below Average
24	Raccoon Creek upstream					74 Average	81 Good	76 Average	72 Average	60 Below Average	67 Below Average	67 Below Average	73 Average	75 Average
25	Raccoon Creek downstream					81 Good	76 Average	81 Good	76 Average	71 Average	73 Average	73 Average	71 Average	77 Average

Volunteer Water Information Network Summary - Haywood County, 1996 - 2008														
Site	Stream	Year 1 1996-97	Year 2 1997-98	Year 3 1998-99	Year 4 1999-00	Year 5 2000-01	Year 6 2001-02	Year 7 2002-03	Year 8 2003-04	Year 9 2004-05	Year 10 2005-06	Year 11 2006-07	Year 12 2007-08	Year 13 2008-09
10	Richland Creek upstream	86 Good	89 Good	89 Excellent	88 Good	87 Good	80 Good	80 Good	85 Good	85 Good	85 Good	91 Excellent	91 Excellent	91 Excellent
11	Richland Creek at Lake Junaluska	80 Good	82 Good	80 Good	69 Below Average	69 Below Average	66 Below Average	88 Good	90 Excellent	87 Good	87 Good	95 Excellent	83 Good	83 Good
27	Jonathan Creek in Maggie Valley					94 Excellent	97 Excellent	97 Excellent	78 Average	78 Average	76 Average	81 Good	81 Good	81 Good
12	Jonathan Creek downstream	80 Good	75 Average	75 Average	71 Average	69 Below Average	69 Below Average	78 Average	78 Average	91 Excellent	87 Good	83 Good	81 Good	81 Good
Average for this group		84	86	81	72	72	71	73	73	72	67	73	73	73
Rural Northeastern Watersheds														
32	Beaverdam Crfeek upstream												70 Average	72 Average
31	Beaverdam Creek downstream												82 Good	82 Good
20	Cove Creek (Fines Creek watershed)				56 Poor	57 Poor	57 Poor	62 Below Average	58 Poor	58 Poor	58 Poor	58 Poor	58 Poor	58 Poor
26	Crabtree Creek					83 Good	70 Average	72 Average	72 Average	75 Average	75 Average	71 Average	79 Average	75 Average
19	Fines Creek upstream				63 Below Average	65 Below Average	65 Below Average	69 Below Average	69 Below Average	65 Below Average	65 Below Average	67 Below Average	67 Below Average	67 Below Average
15	Fines Creek midstream		75 Average	73 Average	58 Poor	66 Below Average	60 Below Average	60 Below Average	59 Poor	55 Poor	64 Below Average	60 Below Average	64 Below Average	64 Below Average
7	Fines Creek downstream	68 Below Average	71 Average	55 Poor	49 Poor	59 Poor	54 Poor	67 Below Average	70 Average	66 Below Average	66 Below Average	66 Below Average	72 Average	68 Below Average

Volunteer Water Information Network Summary - Haywood County, 1996 - 2008														
Site	Stream	Year 1 1996-97	Year 2 1997-98	Year 3 1998-99	Year 4 1999-00	Year 5 2000-01	Year 6 2001-02	Year 7 2002-03	Year 8 2003-04	Year 9 2004-05	Year 10 2005-06	Year 11 2006-07	Year 12 2007-08	Year 13 2008-09
14	Rush Fork upstream (Crabtree Creek watershed)		75 Average	66 Below Average	60 Below Average	62 Below Average	58 Poor	62 Below Average	65 Below Average	60 Below Average	60 Below Average	60 Below Average	60 Below Average	60 Below Average
6	Rush Fork downstream (Crabtree Creek watershed)	66 Below Average	61 Below Average	50 Poor	58 Poor	55 Poor	55 Poor	55 Poor	53 Poor	69 Below Average	79 Average	76 Average	78 Average	78 Average
Average for this group		67	71	61	57	64	60	64	64	64	67	65	70	69
Pigeon River and Upper Forks														
2	East Fork Pigeon River at Bethel	93 Excellent	84 Good	93 Excellent	92 Excellent	92 Excellent	92 Excellent	100 Excellent	100 Excellent	100 Excellent	100 Excellent	100 Excellent	100 Excellent	100 Excellent
3	East Fork Pigeon River at Cruso	100 Excellent	100 Excellent	100 Excellent	100 Excellent	98 Excellent	98 Excellent	98 Excellent	100 Excellent	100 Excellent	98 Excellent	98 Excellent	96 Excellent	96 Excellent
4	Pigeon River downstream from Canton	68 Below Average	61 Below Average	55 Poor	60 Below Average	60 Below Average	60 Below Average	74 Average	68 Below Average	72 Average	75 Average	74 Average	72 Average	72 Average
5	Pigeon River at Hepco Bridge	73 Average	73 Average	55 Poor	46 Poor	38 Poor	48 Poor	63 Below Average	63 Below Average	77 Average	69 Below Average	69 Below Average	66 Below Average	66 Below Average
1	West Fork Pigeon River at Bethel	93 Excellent	96 Excellent	96 Excellent	98 Excellent	98 Excellent	95 Excellent	98 Excellent	98 Excellent	98 Excellent	100 Excellent	100 Excellent	100 Excellent	100 Excellent
16	Sorrell's Creek (upstream of fish farm)		96 Excellent	96 Excellent										
17	Sorrell's Creek downstream of fish farm)		84 Good	84 Good										
18	Sorrell's Creek (effluent of fish farm)			89 Good										
Average for this group		85	85	84	79	77	79	87	86	89	88	88	87	87